


RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Installation Manual and Datasheet

<http://www.rhinomc.com>

Parallel Port Buffered Breakout Board V2[RMCS-2401]

Page 1

RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Key Features

- All inputs and outputs are buffered
- Optoisolated Spindle control capable of taking PWM input
- Both terminals of spindle optocoupler are available on screw terminal
- 2 Relays on board with NO, NC and Com connections on screw terminal, can be used for spindle, coolant and other high voltage/current applications.
- USB power input- No special power needed for operation for using without relays. 12V power input can be given from screw terminal or DC jack.
- All inputs and outputs except spindle & relays can be used for other operations by software settings
- Simple but efficient and cost effective solution for PC based CNC control
- Inbuilt resistor for limit/proximity switch input
- NPN type proximity switch/Reed switch/Limit switch can be used for inputs
- Suitable for small and medium size 3 and 4 axis machines
- No settings on hardware level, everything can be set from software
- Small form factor
- Multiple boards can be used with multiple parallel ports by adding PCI cards in PC for expanding IOs

Description

Thank you for purchasing RMCS-2401, Parallel Port Breakout Board for CNC applications. This board can be used to control CNC machines which use 3 Stepper or Servo motors. The drives for steppers or servos must have impulse (step & direction) input. Only 3 connections are required for each drive – Step, Direction and GND.

The RMCS-2401 is completely buffered and can control the machine at distance of upto 4 meters away from PC without any problem at maximum pulse rate possible. So to make a CNC working you need just 3 + RMCS-2401 + Limit switches + Power supply for drives.

RHINO MOTION CONTROLS


RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Board Pinouts and Connections



Board dimensions : 58 X 82.5 mm
Holes : 2.2 mm inside from edge

Parallel port Pins 2-9,14,16 are outputs &
Pins 10-13, 15 are inputs

- **OUTPUT PINS**
- **INPUT PINS**
- **GND**
- **POWER PINS/CONNECTOR**

Notes :

1. Pin description is just suggestion. Any input or output pins (except relay and opto) can be used for any purpose programmed in software.
For example Pin 2 is shown for X-step but it can be used for Y-step and Pin 4 can be used for X-step instead. Same for input pins.

2. Relays are operated from 12V power supply input through either screw terminal (12V input) or DC jack. USB power can be used if relays are not required in system.

3. Do not use both 12V input and USB power simultaneously.

4. Check all connections properly before powering up.

5. Power up board after PC software is running and ready.

RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Connections : Connecting Stepper/Servo drives

Stepper or Servo drive can be connected with Step & Direction input interface.

Connect Step(step+/Pulse+) and Direction(Dir+) pin to output pin i.e. X_Step & X_Dir
Connect Common/-Ve/Step-/Pulse- or Dir- pin to GND


If there is enable pin compulsory to connect on drive you can connect it to +5V output and GND otherwise you can keep it open.

Connections : Connecting Relays

2 Relays are already on board with all connections coming to screw terminals.

Extra Relay can be connected to any output pin i.e. Coolant_Mist for switching of high loads like pumps, motor or lights etc.

External power supply for powering up relay is required in this case. Rating depends on type of relay.
A 1K Ω resistor and an NPN transistor (BC547,TIP122,2N3904) is required to switch relay from board signal.



Connections : Connecting Limit Switches

Limit switches can be connected directly between input pin and GND pin. Switches can be paralleled to get multiple inputs on one axis. As the pins are internally buffered and pulled up, no optoisolation or power is required. Switches should be connected to NO config. If you are using NC Active Low should be disabled in input signal.

RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Connections : Connecting Proximity Switches/Sensors

Any NPN proximity switch or sensor can be connected between Input pin and GND. Output of sensor should be given to input pin and GND should be connected to GND of proxy. Proximity switch requires external power supply. You may put a 1K resistor in series between output of sensor and input pin.

Multiple proximity switches may be paralalled to get multiple input on single Input line.

Connections : Connecting Spindle (PWM/Non PWM mode)

This board directly supports VFD drives for spindle control. An optoisolated output is connected to Spindle_E and Spindle_C terminals. Many drives also support step and direction input or speed input through PWM signal. Softwares like Mach3 can generate PWM signal for controlling spindle speed. For more information see your VFD drive documentation and Mach3 documentation (available here :

<http://www.machsupport.com/help-learning/product-manuals/>)

RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Configuring Mach3

To demonstrate normal functionality of board we have chosen Mach3 software as standard demo software to demonstrate the features and configurations of this board.

Mach3 trial version is available here : <http://www.machsupport.com/software/mach3/>

It's also available for purchase. Trial version can process only 500 lines of G-Code.

It's very important to make your parallel port working with Mach3 or other software.

Mach3 doesn't support 64 bit windows and some version of Windows after Windows 7. You may try to run it in compatibility mode. Its required to check that parallel port driver is installed and functioning properly.


To check wheather mach3 can access your parallel port or not connect a LED between Pin2 and GND of parallel port, Pin2 should be +ve of LED. When step input is given the LED should glow depending on the speed of pulses. If this is not happening board will not work as there will be no input from parallel port. There may be several reasons for this but mainly it may be because of driver or configuration of Mach3.

Note that USB to parallel port cables will not work with Mach3. If you don't have parallel port in your pc you may use a PCI parallel port card.

After installing Mach3 and restarting PC (if it's asked to do) you can start configuring Mach3.

Step 1: Set native units

Start with Mach3 Mill profile. Go to Config menu -> Set native units and select mm or inches whatever you prefer



<http://www.rhinomc.com>

RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC


Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Step 2: Set parallel port address


If your pc has parallel port by default it should be LPT1 and address 0x378. But if you have more than 1 parallel port or no parallel port and you have added PCI card you may need to see the address of your port. BIOS setting may also change parallel port number. To see address of parallel port -

Go to Control Panel -> System -> Device Manager -> Ports (COM & LPT) -> Double click Parallel/Printer Port, goto resources tab



The first number in I/O range parameter is your parallel port address.

In Mach3 Go to Config Menu -> Ports and Pins set the parallel port address in Port 1. Default is 0x378.



Also set the Kernel Speed to 100Khz for good performance.

<http://www.rhinomc.com>

RHINO MOTION CONTROLS

RMCS-2401


Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Step 3: Set Pin mappings for board (Motor Outputs)

Goto motor output tab in Ports and Pins. For 3 axis machine enable X,Y and Z axis and enter addresses as shown in figure. A axis is not supported by this board and just shown for reference in image.



This is just for showing application but you can assign any pin for any output and connect output connections from board accordingly.

Also spindle step can be set to Pin 8 and Direction to Pin 9 to enable direction and speed control for spindle. More options for spindle can be found in Spindle Setup. See Mach3 user manual for detailed description.




Step 3: Set Pin mappings for board (Other Outputs)

Output signals tab can be used to configure extra outputs like Enable and other outputs which include spindle, coolant or extra relays. Detailed settings can be found in Spindle setup. See mach3 guide for more details.

Step 4: Set Pin mappings for board (Switch Inputs)

Limit switches or Proximity switches/sensors can be used to sense machine limits. When these inputs are detected Mach3 will stop giving pulses to motor. This will stop motors from damaging machine if its going out of mechanical limits. Set the inputs as per figure below. Make sure that you make it Active Low enabled. You can also go to automated setup of inputs and trigger each switch manually to configure.



In the same screen, Estop and other inputs can be configured.

There are many more other settings in Mach3 which are out of scope of this document. You can see Mach3 forums and guides for detailed instructions or troubleshooting.

RHINO MOTION CONTROLS

RMCS-2401


Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Step 5: Motor tuning

Now when all outputs and Limit switches are connected its time to configure that motors are moving perfectly as per input from software. To tune this you can go to Config -> Motor tuning.



First important step is to set Steps per Unit. If you have a linear axis with ball screw of pitch 5 mm, in one rotation of your motor guide will go 5 mm further. Same way if you have set microstepping of 800 steps per revolution, 800 steps will give you 1 rotation = 5 mm of travel.

Maximum velocity is the maximum possible speed of motor with some margin, you can set this upto 80% of maximum speed of motor to avoid accidents. Maximum velocity and acceleration should be checked with trial and error of your setup.

Don't forget to click SAVE AXIS SETTINGS before quitting the menu or switching to other Axis. Configure all Axis properly and you are ready to go.

RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Mach3 is an extremely complicated software with hundreds of more features shown in this document. See http://www.machsupport.com/wp-content/uploads/2013/02/Mach3Mill_1.84.pdf for more information.

There are hundreds of settings and parameters to customize your machine and so it's must that you read all documents properly before setting this board.

The RMCS 2401 can be used with any other software which gives step and direction output for CNC control on parallel port. Config can be found in help of the software.

RHINO MOTION CONTROLS

RMCS-2401

Parallel Port Buffered Breakout Board for 3 Axis CNC

Usable with Mach3, EMC2, TurboCNC and other CNC softwares



Service and Support

Service and support for this product are available from the Rhino Motion Controls Web site (<http://www.rhinomc.com>) and our customer service email: info@rhinomc.com

Six-Month Warranty

Rhino Motion Controls (rhinomc.com) warrants its products against defects in materials and workmanship for a period of 6 months from shipment delivery. During the warranty period, Rhino Motion Controls will either, at its option, repair or replace products which proved to be defective.

Exclusions

The above warranty does not extend to any product damaged by reasons of improper or inadequate handlings by customer, improper or inadequate customer wirings, unauthorized modification or misuse, or operation beyond the electrical specifications of the product and/or operation beyond environmental specifications for the product.

Obtaining Warranty Service

To obtain warranty service, please contact our customer service department at info@rhinomc.com before returning product for service. Please make sure that you have gone through this entire installation manual and datasheet before deciding that your product is liable for replacement or repair under this 6-month warranty. Customer shall prepay shipping charges for products returned to Rhino Motion Controls for warranty service, and Rhino Motion Controls shall pay for return of products to customer.

Warranty Limitations

Rhino Motion Controls makes no other warranty, either expressed or implied, with respect to the product. Rhino Motion Controls specifically disclaims the implied warranties of merchantability and fitness for a particular purpose. Some jurisdictions do not allow limitations on how long and implied warranty lasts, so the above limitation or exclusion may not apply to you. However, any implied warranty of merchantability or fitness is limited to the 6-month duration of this written warranty.

Disclaimer

Copyright © Rhino Motion Controls, 2014

Neither the whole nor any part of the information contained in, or the product described in this manual, may be adapted or reproduced in any material or electronic form without the prior written consent of the copyright holder.

This product and its documentation are supplied on an as-is basis and no warranty as to their suitability for any particular purpose is either made or implied.

This document provides preliminary information that may be subject to change without notice.